CLEAR65
Proposition 65 warning paperwork

Sensen

Proposition 65 compliance file

Generated Nov 22, 2026, 4:25 AM PST
File status: Draft, review incomplete

What this file contains

Product family determinations, the warning materials selected for each family, retailer notices prepared under 27 CCR 25600.2, receipt confirmations, and the manual listing checks recorded for this brand.

Basis: material family knowledge. No laboratory testing, sample handling, or test reports are included in this version. Each determination records the human reviewer who signed it.

1. Product family determinations

Shocks and struts

Draft | 3 products | Not ready

PROP 65 PRODUCT DETERMINATION

Brand: Sensen
Product family: Shocks and struts
Determination status: Draft, awaiting reviewer

Materials considered:
- Steel body and rod
- Hydraulic oil
- Rubber bushings and seals
- Paint or coating
- Plastic dust boot

Likely listed chemicals:
- Lead and lead compounds
- Di(2-ethylhexyl) phthalate (DEHP)
- Diisononyl phthalate (DINP)

Route: Warn
Basis: Material family knowledge. No laboratory testing was performed for this version.
Reasoning: Steel, hydraulic oil, rubber bushings, and painted surfaces are common sources of lead and phthalates in shocks and struts.

Reviewer: not signed off
Review date: not recorded

Products in this family:

Strut Assembly, Front, Honda Accord | SKU 3213-0211 | UPC 049797321119
Shock Absorber, Front, Toyota Camry | SKU 4214-0149 | UPC 049797421491
Shock Absorber, Rear, Toyota Camry | SKU 4214-0150 | UPC 049797421507

2. Warning text

Shocks and struts

Motor vehicle parts warning (tailored)

WARNING: Handling passenger or off-highway motor vehicle parts can expose you to chemicals such as phthalates and lead, which can cause cancer and reproductive harm. To minimize exposure, service the vehicle in a well-ventilated area, wear gloves, and wash your hands. For more information see P65Warnings.ca.gov/motor-vehicle-parts.

Short form for labels

WARNING: Risk of cancer and reproductive harm from exposure to lead. See www.P65Warnings.ca.gov.

Not locked

3. Retailer notices and receipts

RockAuto

Not started

No notice has been generated for this retailer.

Receipt
Pending

Amazon

Not started

No notice has been generated for this retailer.

Receipt
Pending

Walmart

Not started

No notice has been generated for this retailer.

Receipt
Pending

AutoZone

Not started

No notice has been generated for this retailer.

Receipt
Pending

O'Reilly Auto Parts

Not started

No notice has been generated for this retailer.

Receipt
Pending

Advance Auto Parts

Not started

No notice has been generated for this retailer.

Receipt
Pending

NAPA Auto Parts

Not started

No notice has been generated for this retailer.

Receipt
Pending

---

4. File record

Brand account: Sensen | Grace Lin | grace@sensen.example
Products in file: 3
Product families: 1
Retailers with a notice: 0 of 7
Reviewer signoffs: 0 of 1 families

This file is prepared for the brand to keep. Notices in this file are prepared for human review and submission. Clear65 does not contact retailers.