CLEAR65
Proposition 65 warning paperwork

StrongArm

Proposition 65 compliance file

Generated Nov 22, 2026, 4:25 AM PST
File status: Active file

What this file contains

Product family determinations, the warning materials selected for each family, retailer notices prepared under 27 CCR 25600.2, receipt confirmations, and the manual listing checks recorded for this brand.

Basis: material family knowledge. No laboratory testing, sample handling, or test reports are included in this version. Each determination records the human reviewer who signed it.

1. Product family determinations

Lift supports

Approved | 6 products | Ready for notices

PROP 65 PRODUCT DETERMINATION

Brand: StrongArm
Product family: Lift supports
Determination status: Approved by reviewer

Materials considered:
- Steel tube and rod
- Zinc or chrome plating
- Rubber seals and end fittings
- Hydraulic oil
- Paint or coating

Likely listed chemicals:
- Lead and lead compounds
- Di(2-ethylhexyl) phthalate (DEHP)
- Diisononyl phthalate (DINP)

Route: Warn
Basis: Material family knowledge. No laboratory testing was performed for this version.
Reasoning: Metal plating, painted steel, rubber seals, and hydraulic oil are common sources of lead and phthalate exposure in lift supports.

Reviewer: M. Alvarez
Review date: Nov 18, 2026
Review note: Material family and warning language reviewed. Approved for retailer notices.

Products in this family:

Lift Support, Toyota Camry 2007-2011 | SKU 4501 | UPC 081234567890
Lift Support, Honda Accord 2008-2012 | SKU 4502 | UPC 081234567891
Lift Support, Toyota Corolla 2009-2013 | SKU 4503 | UPC 081234567892
Lift Support, Ford F-150 2009-2014 | SKU 4510 | UPC 081234567893
Lift Support, Chevrolet Silverado 2007-2013 | SKU 4520 | UPC 081234567894
Lift Support, Nissan Altima 2007-2012 | SKU 4530 | UPC 081234567895

2. Warning text

Lift supports

Motor vehicle parts warning (tailored)

WARNING: Handling passenger or off-highway motor vehicle parts can expose you to chemicals such as phthalates and lead, which can cause cancer and reproductive harm. To minimize exposure, service the vehicle in a well-ventilated area, wear gloves, and wash your hands. For more information see P65Warnings.ca.gov/motor-vehicle-parts.

Short form for labels

WARNING: Risk of cancer and reproductive harm from exposure to lead. See www.P65Warnings.ca.gov.

Locked Nov 18, 2026

3. Retailer notices and receipts

RockAuto

Draft ready

NOTICE OF PROPOSITION 65 WARNING MATERIALS
Submitted under California Code of Regulations, Title 27, Section 25600.2

Date sent: Not yet sent
Retailer: RockAuto
Authorized agent company: To be completed
Agent contact: To be completed
Agent email: To be completed
Agent address: To be completed

From: StrongArm
Brand contact: Dana Ruiz
Brand email: dana@strongarm.example

Re: Proposition 65 warning materials for StrongArm products listed below

StrongArm is providing the following warning materials for the products identified by UPC. The warning materials apply to these products when offered for sale in California.

PRODUCTS COVERED
Lift Support, Toyota Camry 2007-2011 | SKU 4501 | UPC 081234567890 | Lift supports
Lift Support, Honda Accord 2008-2012 | SKU 4502 | UPC 081234567891 | Lift supports
Lift Support, Toyota Corolla 2009-2013 | SKU 4503 | UPC 081234567892 | Lift supports
Lift Support, Ford F-150 2009-2014 | SKU 4510 | UPC 081234567893 | Lift supports
Lift Support, Chevrolet Silverado 2007-2013 | SKU 4520 | UPC 081234567894 | Lift supports
Lift Support, Nissan Altima 2007-2012 | SKU 4530 | UPC 081234567895 | Lift supports

WARNING MATERIALS
Lift supports

Motor vehicle parts warning (tailored):

WARNING: Handling passenger or off-highway motor vehicle parts can expose you to chemicals such as phthalates and lead, which can cause cancer and reproductive harm. To minimize exposure, service the vehicle in a well-ventilated area, wear gloves, and wash your hands. For more information see P65Warnings.ca.gov/motor-vehicle-parts.

Short form for labels:
WARNING: Risk of cancer and reproductive harm from exposure to lead. See www.P65Warnings.ca.gov.

RECEIPT
Receipt: pending

Prepared by Clear65 for review and signature by the brand before submission. This tool does not contact the retailer.

Receipt
Pending

Amazon

Not started

No notice has been generated for this retailer.

Receipt
Pending

Walmart

Not started

No notice has been generated for this retailer.

Receipt
Pending

AutoZone

Verified unblocked | Sent Oct 20, 2026 | Renewal Oct 20, 2027

NOTICE OF PROPOSITION 65 WARNING MATERIALS
Submitted under California Code of Regulations, Title 27, Section 25600.2

Date sent: Oct 20, 2026
Retailer: AutoZone
Authorized agent company: AutoZone authorized agent (demo entry)
Agent contact: Compliance intake
Agent email: compliance@autozone.example
Agent address: Demo address on file

From: StrongArm
Brand contact: Dana Ruiz
Brand email: dana@strongarm.example

Re: Proposition 65 warning materials for StrongArm products listed below

StrongArm is providing the following warning materials for the products identified by UPC. The warning materials apply to these products when offered for sale in California.

PRODUCTS COVERED
Lift Support, Toyota Camry 2007-2011 | SKU 4501 | UPC 081234567890 | Lift supports
Lift Support, Honda Accord 2008-2012 | SKU 4502 | UPC 081234567891 | Lift supports
Lift Support, Toyota Corolla 2009-2013 | SKU 4503 | UPC 081234567892 | Lift supports
Lift Support, Ford F-150 2009-2014 | SKU 4510 | UPC 081234567893 | Lift supports
Lift Support, Chevrolet Silverado 2007-2013 | SKU 4520 | UPC 081234567894 | Lift supports
Lift Support, Nissan Altima 2007-2012 | SKU 4530 | UPC 081234567895 | Lift supports

WARNING MATERIALS
Lift supports

Motor vehicle parts warning (tailored):
WARNING: Handling passenger or off-highway motor vehicle parts can expose you to chemicals such as phthalates and lead, which can cause cancer and reproductive harm. To minimize exposure, service the vehicle in a well-ventilated area, wear gloves, and wash your hands. For more information see P65Warnings.ca.gov/motor-vehicle-parts.

Short form for labels:
WARNING: Risk of cancer and reproductive harm from exposure to lead. See www.P65Warnings.ca.gov.

RECEIPT
Receipt confirmed: Oct 24, 2026, 10:30 AM PDT
Receipt ID AZ-2026-1042. Notice received October 24, 2026. Demo receipt for this example.

Prepared by Clear65 for review and signature by the brand before submission. This tool does not contact the retailer.

Receipt
Confirmed Oct 24, 2026, 10:30 AM PDT
Receipt ID AZ-2026-1042. Notice received October 24, 2026. Demo receipt for this example.
Attached receipt file: autozone-receipt-demo.txt

Manual listing checks
4501 | 081234567890 | Block gone | Ships to California
4502 | 081234567891 | Block gone | Ships to California
4503 | 081234567892 | Block gone | Ships to California
4510 | 081234567893 | Block gone | Ships to California
4520 | 081234567894 | Block gone | Ships to California
4530 | 081234567895 | Block gone | Ships to California

O'Reilly Auto Parts
Not started

No notice has been generated for this retailer.

Receipt
Pending

Advance Auto Parts
Not started

No notice has been generated for this retailer.

Receipt
Pending

NAPA Auto Parts
Not started

No notice has been generated for this retailer.

Receipt
Pending

4. File record

Brand account: StrongArm | Dana Ruiz | dana@strongarm.example
Products in file: 6
Product families: 1
Retailers with a notice: 2 of 7
Reviewer signoffs: 1 of 1 families (M. Alvarez, Nov 18, 2026)

This file is prepared for the brand to keep. Notices in this file are prepared for human review and submission. Clear65 does not

contact retailers.